



Deployment and Implementation of Kadence



194 Traffic Incident Management led to development of an alternative plan







2023-24 Kadence Deployment

- TIM operation advantage
- Major backup on 2 lane arterial during incident
- Plymouth Rd is a major arterial into the City of Ann Arbor and hospitals





















Esri Community Maps Contributors, Province of Ontario, SEMCOG, @ OpenStreetMap, Microsoft, Esri, H... Powered by Esri

Traffic Signal Repair

Created Date: 10/11/2023 2:08 PM

W Textile Rd & E Silo Ridge Dr Ann Arbor, Michigan, 48108

Details

Traffic Sign - Repair: Officer Mark Haddow with Pittsfield Twp says the crosswalk sign is missing from the southside of the road on Textile east of Silo Ridge.

Secondary Questions

Please provide the road and cross street and/or additional location information.

Textile east of Silo Ridge

What is the sign issue?

Missing

What color is the sign?

Yellow

What type of sign? (e.g. yield, speed limit)

Crosswalk

Please provide your name and phone number in case additional information is needed. This information will NOT be publicly displayed.

Officer Mark Haddow, (734) 368-8059



Subscribers

Unsubscribe

Communications Manager - Tiffany	
T & S - Signals Engineer	
T & S - Signs	

Status Log

Opened:	10/11/2023 2:08 PM
Acknowledged:	10/12/2023 9:36 AM

Work Orders

New Work Order

What's next for WCRC

- Status Dashboard
 - Provide high-level status of stakeholder signals
- Traction Workflow
 - Provides up-to-minute status of work orders to technicians and engineer
- TSP for the City of Ann Arbor and WCRC collaboration







